



SSM 53041 2024 Nautilus - Front Exterior Farewell Grille Lighting Event Randomly Occuring 30-60 Minutes After The Vehicle Is Parked - Built On Or Before 01-May-2024

Some 2024 Nautilus vehicles built on or before 01-May-2024 may exhibit a front exterior farewell grille lighting event randomly occuring 30-60 minutes after the vehicle is parked. This may be due to the software in the lighting driver control module (LDCM). To address this condition, reprogram the LDCMA (LH headlamp) and LDCMB (RH headlamp) using the Ford Diagnosis and Repair System (FDRS) > Lighting Driver Control Module Software Updates. For claiming, use causal part 13008 and applicable labor operations in section 10 of the Service Labor Time Standards (SLTS) manual. Optionally, claim additional programming (AP) time as needed.