



Bulletin No.: PIP6007

Published date: N/A

Preliminary Information

PIP6007 Diagnostic Tip: DTC P2B81 Set As Current Or In History

Proactive

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Envista	2021 - 2024	All	All 2.0 LSY	All
Cadillac	CT4	2020 - 2024	All	All 2.0 LSY	All
Cadillac	CT5	2020 - 2024	All	All 2.0 LSY	All
Cadillac	XT4	2019 - 2024	All	All 2.0 LSY	All
Cadillac	XT5	2020 - 2024	All	All 2.0 LSY	All
Cadillac	XT6	2020 - 2024	All	All 2.0 LSY	All
Chevrolet	Blazer	2020 - 2024	All	All 2.0 LSY	All

Involved Region or Country:	North America
Condition:	DTC P2B81 set as current or in history.
Cause:	Increased friction in wastegate valve.

Correction

If you encounter one of the above mentioned vehicles with DTC P2B81 set as current or in history this may be due to increased friction within the wastegate valve and will require turbocharger replacement.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation:	Description	Labor Time:
4088858	Replace Turbocharger for Binding	4.9 Hr.

Version History

Version	1
Modified	09/13/2024 - Created on.