



Bulletin No.: PIT5812E
Published date: 09/18/2024

Preliminary Information

PIT5812E Grind Noise From Brakes

Proactive

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Equinox	2021 - 2023	All All	All	All
GMC	Terrain	2021 - 2023	All All	All	All

Involved Region or Country:	North America
Condition:	Grinding noise on brake apply cold that dissipates after a few stops.
Cause:	New no copper pad composition.

Engineering is investigating this concern and working towards a resolution which is expected in calendar year 2024.

Replacing pads will not eliminate this concern for the long term.

Deglazing the pads and rotors does help the concern in the short term.

This PI will be removed and a bulletin released when the field fix is available.

Version History

Version	6
Modified	<p>02/02/2021 - Created on.</p> <p>05/10/2021 - Revised to add models.</p> <p>06/30/2021 - Removed Colorado and Canyon models due to the release of 21-NA-142</p> <p>03/15/2022 - Added 2022 model year.</p> <p>02/24/2023- Added 2023 model year and expected resolution date.</p> <p>08/18/2024 - Updated to add model year 2024</p>