



Bulletin No.: PIT6240

Published date: 09/20/2024

Preliminary Information

PIT6240 Adding Fast (High) Idle RPO UF3

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Silverado 2500HD/3500HD	2007 - 2025	All All	All	All
Chevrolet	Silverado 4500HD, 5500HD, 6500HD	2019 - 2024	All All	All	All
GMC	Sierra 2500/3500	2007 - 2025	All All	All	All

Involved Region or Country	North America
Additional Options (RPO)	Cruise Control RPO K34 or Adaptive Cruise Control RPO KSG.
Condition	A Dealer or Upfitter may be looking for information on adding Fast (High) Idle RPO UF3 to a vehicle.
Cause	Information not readily available in Service Information (SI).

Correction:

Reference the latest version of GM Upfitter Integration Bulletin 82. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

NOTE: For 2024 and newer Silverado 2500HD/3500HD / Sierra 2500HD/3500HD models an additional SPS ECM Setup procedure is required to fully activate the feature. Reference latest version of GM Upfitter Integration Bulletin 82 for details.

Version History

Version	1
Modified	09/20/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.