



**Bulletin No.:** PIP6007A

**Published date:** 09/23/2024

## Preliminary Information

### PIP6007A Diagnostic Tip: DTC P2B81 Set As Current Or In History

#### Proactive

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Buick	Envision	2021 - 2025	All	All 2.0 LSY	All
Cadillac	CT4	2020 - 2025	All	All 2.0 LSY	All
Cadillac	CT5	2020 - 2025	All	All 2.0 LSY	All
Cadillac	XT4	2019 - 2025	All	All 2.0 LSY	All
Cadillac	XT5	2020 - 2025	All	All 2.0 LSY	All
Cadillac	XT6	2020 - 2025	All	All 2.0 LSY	All
Chevrolet	Blazer	2020 - 2025	All	All 2.0 LSY	All

<b>Involved Region or Country:</b>	<b>North America</b>
<b>Condition:</b>	<b>DTC P2B81 set as current or in history.</b>
<b>Cause:</b>	<b>Increased friction in wastegate valve.</b>

#### Correction

If you encounter one of the above mentioned vehicles with DTC P2B81 set as current or in history this may be due to increased friction within the wastegate valve and will require turbocharger replacement.

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

<b>Labor Operation:</b>	<b>Description</b>	<b>Labor Time:</b>
<b>4088858</b>	<b>Replace Turbocharger for Binding</b>	<b>4.9 Hr.</b>

#### Version History

<b>Version</b>	<b>2</b>
<b>Modified</b>	<b>09/13/2024 - Created on. 09/23/2024 Updated to correct Envista error and add 2025 Model Year</b>