



**Bulletin No.:** PIT6227A  
**Published date:** 09/25/2024

## Preliminary Information

### PIT6227A Service Occupant Motion Detection System Message Displayed At Times

#### Models

**Brand:** Chevrolet **Model:** Equinox EV **Model Years:** 2024 **VIN:** All **from to:** All All **Engine:** All **Transmissions:** All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	<b>Service Occupant Monitor System displayed on Instrument Panel Cluster.</b>
<b>Cause</b>	<b>Body Control Module has an incorrect calibration for the application.</b>

#### Correction:

If a vehicle is found to intermittently display a "Service Occupant Monitor System" message on the dash.

Please perform the VWP (vehicle wide programming) accessed through Techline Connect.

#### Version History

<b>Version</b>	<b>2</b>
<b>Modified</b>	<b>08/26/2024 - Created on. 09/25/2024- Updated correction with updated information.</b>