



Service Bulletin

Bulletin No.: 24-NA-049

Date: September, 2024

INFORMATION

Subject: Information on Blazer EV Police Vehicle Air Deflector Installation

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer EV	2024	2025	-	-	All	All


Involved Region or Country	North America
Condition	On Blazer EV POLICE vehicles during PDI the dealer may find that the front air deflectors are too long and interfere with an underbody shield.
Cause	The cause of the condition may be due to the aero panel was added after the air deflectors were developed.
Correction	Trim the air deflectors like illustrated below.

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Important: This technical service bulletin (TSB) can only be completed by certified repair facilities who have met all specific training, tool and equipment requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.

If you encounter a vehicle with the above concern, trim the air deflectors in the locations illustrated below.



6576071



6576072

Parts Information

No parts are required for this repair.

Version	2
Modified	Released March 15, 2024 Revised September 17, 2024 – Added 2025 Model Year.

