



# Technical Service Bulletin

## 43 DTC B200FF is stored in the J775

43 24 97 2051336/8 September 9, 2024. Supersedes Technical Service Bulletin Group 43 number 23-73 dated May 19, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, and A4 allroad	2017 – 2025	All	Suspension with Electronic Damper Control
S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, and S5 Sportback	2018 – 2025		
RS 5	2018 – 2019 2021 – 2025		
RS 5 Sportback	2019 2021 – 2025		

## Condition

REVISION HISTORY		
Revision	Date	Purpose
8	-	Revised header (Added model year) Revised <i>Service</i> (Updated Information) Revised <i>Warranty</i> (Updated Information)
7	05/19/2023	Revised header (Added model year)
6	06/07/2022	Revised header (Added model year)

### Customer states:

- A fault in the damping control is indicated in the instrument cluster.

### Workshop findings:

- The DTC **B200FF0** (internal malfunction) is stored in the J775 (address word 0074).

## Technical Background 1

The conditions for the DTC apply.



# Technical Service Bulletin

## Production Solution

Not applicable.

## Service

The DTC does not affect the handling characteristics of the vehicle.

Perform steps in the GFF, if no discrepancies occur, perform basic settings of the J775 and delete the DTC (Use *Guided Function 0074 – Basic Settings Complete* for the basic settings).

It is not necessary to replace the control unit.

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
<b>Service Number:</b>	4316		
<b>Damage Code:</b>	0040		
<b>Labor Operations:</b>	GFF	0150 0000	Time stated on the diagnostic protocol
	Charge Battery	2706 8950	See SRT with associated operations
	Control Unit Setting Performed	4316 1550	See SRT with associated operations
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB 2051336/8		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All parts and service references provided in this TSB (2051336) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any



# Technical Service Bulletin

---

time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.