



# Technical Service Bulletin

## 93 PSS e-tron GT: yellow electrical system fault - U019B00 logged in diagnostic address 0019

93 24 19 2075400/2 September 25, 2024. Supersedes Technical Service Bulletin Group 93 number 24-18 dated September 24, 2024 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2025	All	Not Applicable

### Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Corrected visibility issue)
1	09/24/2024	Initial publication

**This bulletin applies to MY25 e-tron GT vehicles only.**

#### Customer states:

- Yellow electrical system fault in the instrument cluster.
- Vehicle cannot be started.
- After switching the ignition off and on again the vehicle can be driven again.

#### Workshop findings:

The following DTC is stored in the Gateway control module, J533 (address word 0019):

- **U019B00** – Lost communication with Battery Charger Control Module.

Further DTC entries with the title “Lost communication with High-Voltage Battery Control Module” or similar may be logged in various control units.

A loss of communication between the Battery charger control module and various other control module occurs.

### Technical Background 1

Not applicable.

### Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.



# Technical Service Bulletin

## Service

1. Explain to the customer that we are working on a software solution for this complaint. We do not expect to be able to provide information on the availability of the planned solution before the 1st quarter of 2025 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*).



**Please inform the customer that after switching the ignition off and on again, it will be possible to start the vehicle again.**

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
<b>Service Number:</b>	9352		
<b>Damage Code:</b>	0039		
<b>Labor Operations:</b>	GFF/ Guided Functions	0150 0010	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
<b>Claim Comment:</b>	As per TSB 2075400/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All part and service references provided in this TSB (**2075400**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may



# Technical Service Bulletin

---

these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.