



SSM 53070 2023-2025 Explorer/Aviator - Inoperative Second Row Single Seat Easy Entry Seat Fold Switch.

Some 2023-2025 Explorer/Aviator vehicles may exhibit an inoperative second row single seat easy entry seat fold switch. This may be due to an improper installation of the bezel surrounding the switch, preventing the switch from moving freely after the switch or bezel has been serviced. To install the bezel properly, ensure the front of the bezel is snapped in place prior to securing the clips at the rear of the bezel. If the switch is moving freely within the bezel, continue with normal diagnostics. Refer to Workshop Manual, Section 501-10B.