



## **SSM 53093 2024-2025 F-650/F-750 - Inaccurate Evaporator Temperature Sensor PID Values Displayed In Datalogger**

Some 2024-2025 F-650/F-750 vehicles may display inaccurate parameter identification (PID) values for the evaporator temperature sensor (EVAP\_TEMP) in Ford Diagnostic and Repair System (FDRS) Datalogger when performing FSA 24U10 or Workshop Manual (WSM) diagnostics. Before using the PID values for the evaporator temperature sensor, click on the refresh icon located next to the Run button in the Datalogger app to correct the concern. When the pop-up message appears asking to re-download all the files, select "Yes." This action will refresh the Datalogger and the PID will now display correct temperature values.