

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922



Subject: TRANSMISSION DESIGN CHANGE (PART SUPERSESSION)	Service Alert No.: SA-002/24
	Last Issued : 10/23/2024

BULLETIN NOTES

This service alert supersedes the previously issued service alert(s) listed below. The changes are noted in Red text.

Previous Service Alert(s)	Date(s) Issued:
SA-002/24	01/10/24

APPLICABLE MODLE(S)/VINS

2025 CX-70 (H3T)

2024-2025 CX-90 (H3T)

DESCRIPTION

Due to a manufacturing change, the CX-70/CX-90 transmission has undergone a transmission part design change when replacing the transmission assembly.


Old design originally required a coolant line running to the top of the bell housing, the new design has omitted the hole and need for the coolant line.

The new/superseded design can be used in place of the old/original design and the coolant hose is no longer needed to be used.

Original Design (Transmission Hole Drilled)

New Superseded Design

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



PARTS INFORMATION

Please review Parts Flash 24-01 for part number information

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.