

Parts



Mazda North American Operations
Irvine, CA 92718-2906



REFERENCE NO: RF-24-10

DATE: 10/01/2024

SUBJECT: CX-90/CX-70 Hood Strut Damper Noise

The right-side hood strut features a two-step mechanism for opening and closing. The first step is for general, the second step is for "service mode". When you open the hood, after completing the hood in service mode, the stay damper might rattle because it loses internal pressure support to the hood-fender-strut system.

This is normal operation and not a sign of any malfunction, no parts should be replaced.

[Click here to view a sample video.](#)

YEAR	MODEL	PART NUMBER	DESCRIPTION	NOTE
2024-2025	CX-70 CX-90	KBB3-56-660	STAY (R), DAMPER BONNET	Contains the built-in two-step mechanism