

McLaren 750S – Coolant Degas Spring Band Clamp Check

Bulletin type:	Service Campaign
Reference number:	N/A
Campaign reference:	SCB 28 L 001
Attention:	Retailer Aftersales Managers, Retailer Service Managers, Retailer Service Advisors, Retailer Technicians, Retailer Parts Managers
Affected vehicles:	McLaren 750S Coupe & Spider
Situation:	Check for position of the spring band clamp on the coolant degas hose
Procedure:	Action affected vehicles during PDI or immediately available at the Retailer premises (including stock, demo and showroom vehicles). Please refer to the information outlined in this document to complete the required work
Date:	17 October 2024

This bulletin will cover:

1. Overview
2. Procedure
3. Warranty Information
4. Affected Vehicles

1. Overview

Through continuous product quality monitoring, McLaren Automotive has identified an inconsistency in fitment of the spring band clamp for the coolant degas hose.

McLaren Automotive is instructing Retailers to check the fitment of the spring band clamp, adjust position if needed and report the results of all the vehicles within the supplied VIN range.




Image 1 Overview images of checking location on both Coupe & Spider respectively

2. Procedure

To carry out the required check for the Service Campaign, follow the work instruction in the McLaren Service Portal (MSP) D052371 for 'Check Engine Degas Hose Clip'.

3. Warranty Information

Submit a claim to the McLaren Warranty department following completion of the work, using the following details.

Retailers are required to submit photographs with each claim where the spring band clamp is found out of position.

Description	Repair Time
McLaren 750S - Coolant Degas Spring Band Clamp Check	0.20 hrs

Description	Repair Time
McLaren 750S - Coolant Degas Spring Band Clamp Re-position	0.10 hrs*

* If the spring band clamp is found out of position, attach a photograph to the warranty claim and add an additional labour line in the claim for 0.10 hrs.

4. Vehicles Affected

Affected vehicles will be flagged in the Retailer Portal when next opening a Workshop Visit related to the vehicle. Your Regional Aftersales Manager will also contact you with a VIN list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

The McLaren data classification policy applies to all full time, part-time and fixed term employees of McLaren and all workers including, contractors, consultants, suppliers, and third parties who have access to McLaren data and/or systems. This policy includes all information held by, or on behalf of, McLaren in any form and all information systems/services used by, or used to store data belonging to, McLaren.

Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.