

## Technical Journal

TITLE:

**TPMS Service Required**

<b>REF NO:</b> TJ 37133.1.0	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7515 Polestar		<b>ISSUE DATE:</b> 2024-10-21	<b>STATUS DATE:</b> 2024-10-28
<b>FUNC GROUP:</b> 3674	<b>FUNC DESC:</b> Tire pressure monitoring control system	<b>Page 1 of 2</b>	

**DESCRIPTION:**

If vehicle has message “TPMS service required” after wheel or TPMS sensor change, follow advice under “Service”.

TPMS = Tire Pressure Monitoring System

**CSC** Customer Symptom Codes

Code	Description
LI	Warning lights and chimes/Tire pressure monitoring, Service required warning

**DTC** Diagnostic Trouble Codes

**Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
359							2025-9999		-	202402-999952

**SERVICE:**

To be able to program the TPMS sensors, download Software Product 32302038 then follow the script to learn sensors on respective position.

**Warranty claim info:**

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

# Technical Journal 37133.1.0

## VST Operation Number

VST Operation Number	Description
99922-2	General Reimbursement acc to. TJ

## LABOR TIME:

Labor time subject to change without notice.

## VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support not needed Polestar", use function group 3674.