



Technical Service Bulletin

68 Sun visor lighting not working

68 24 46 2075718/1 October 22, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2020 – 2025	All	Not Applicable

Condition

Customer states:

- Q3 sun visor lighting faulty.

Technical Background 1

On extendible sun visors, the lighting only works if the sun visor is pushed in all the way (Figures 1, 2).



Figure 1. Sun visor fully extended, light off.



Technical Service Bulletin



Figure 2. Sun visor pushed in, light on.

Production Solution

Not applicable.

Service

Please explain to the customer how the extendible sun visor works.

Warranty

This is not a fault which is covered under warranty. Service information is for explaining the lighting function. This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2075718**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.



Technical Service Bulletin

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.