

WRS6 Workshop Campaign - Readjusting control unit for tire pressure monitoring (TPM)

WRS6 Workshop Campaign - Readjusting control unit for tire pressure monitoring (TPM)

ID Number	WRS6
Model(s)	Macan electric (XAB)
Model Year(s)	2024 -2025
VIN List	Attached
Number of Affected VINs	3024
Issue Description	<p>On the affected vehicles there is a possibility that the tire pressure monitoring control unit (TPM) on the affected vehicles has not been coded in accordance with the specifications.</p> <p>For this reason, the tire pressure monitoring control unit (TPM) must be readjust via Porsche Communication Management (PCM).</p>
What Dealers Should Do	Please arrange for this campaign to be carried out on the affected vehicles
TI	Attached

Test instructions and remedial measures

The technical information will be communicated once available

Until the TI is available in the PCSS, the campaign can already be carried out with the instructions in the attachment below.

Please note the information on warranty processing.

Warranty processing

Validity:

This workshop campaign will be carried out up to 07/11/2029 and will be closed by the specified date.

WRS6 Workshop Campaign - Readjusting control unit for tire pressure monitoring (TPM)

Please note that warranty claims can only be processed up to this date.

Scope 1: Readjust control unit for tire pressure monitoring (TPM)

No Final Vehicle Analysis Log (VAL) has yet been created and remunerated as part of the WRM0 campaign. It is not necessary to create a Final Vehicle Analysis Log (VAL) in this campaign. In this case, scope 1 is to be settled in this campaign.

Damage Code	WRS6 66 000
Repair Code	1
Labor time	24 TU

Scope 2: Readjust control unit for tire pressure monitoring (TPM)

A Final Vehicle Analysis Log (VAL) has already been created and remunerated as part of the WRM0 campaign.

A new Final Vehicle Analysis Log (VAL) is required. In this case, scope 2 must be settled in this campaign.

Damage Code	WRS6 66 000
Repair Code	1
Labor time	57 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [WRS6 VIN_List_Report V2 10.07.2024.xlsx](#)
2. [WRS6_Instruction_XAB_EN.pdf](#)