

Subject

**Torque Converter Installation Precaution**

Market

**USA**

Service Category

**Drivetrain**

Section

**Automatic Transmission/Transaxle**

Applicability

**23-24Sequoia HV 22-24Tundra/Tundra HV**

**APPLICABLE VEHICLES**

2022-2024	Tundra	2023-2024	Sequoia HV
2022-2024	Tundra HV		


**CONDITION**

During repairs such as those listed below, damage may occur if the Torque Converter Assembly is not properly installed.

- Hybrid module assembly removal/installation
- Transmission removal/installation
- Engine removal/installation

**RECOMMENDATIONS**

Referring to the appropriate Repair Manual Installation instructions, pay close attention to step #2 for Torque Converter Assembly Installation. It is critical to align the oil pump drive sprocket at the "12-6" o'clock position as indicated in the diagram below **before** installing the Torque Converter cutout to the protrusion on the oil pump.



Subject

**Torque Converter Installation Precaution**

Market

USA

Applicability

**LINK REFERENCES**

1. [L4A0E \(HYBRID TRANSMISSION / TRANSAXLE\): HYBRID VEHICLE TRANSMISSION: INSTALLATION; 2023 - 2024 MY Sequoia HV \[09/2022 - ???????\]](#)
2. [L4A0F \(HYBRID TRANSMISSION / TRANSAXLE\): HYBRID VEHICLE TRANSMISSION: INSTALLATION; 2023 - 2024 MY Sequoia HV \[09/2022 - ???????\]](#)
3. [AJA0E \(AUTOMATIC TRANSMISSION / TRANSAXLE\): AUTOMATIC TRANSMISSION ASSEMBLY: INSTALLATION; 2022 - 2024 MY Tundra \[11/2021 - ???????\]](#)
4. [AJA0F \(AUTOMATIC TRANSMISSION / TRANSAXLE\): AUTOMATIC TRANSMISSION ASSEMBLY: INSTALLATION; 2022 - 2024 MY Tundra \[11/2021 - ???????\]](#)
5. [L4A0E \(HYBRID TRANSMISSION / TRANSAXLE\): HYBRID VEHICLE TRANSMISSION: INSTALLATION; 2022 - 2024 MY Tundra Tundra HV \[05/2022 - ???????\]](#)