

DTNA Solutions > Service Solutions > FCCC
> SS 285 eB2 (Jouley) and MT50e Telemetry Module Com...

SS 285 eB2 (Jouley) and MT50e Telemetry Module Commissioning and Operation

Applicable Vehicles

FCCC eB2 and MT50e

Symptoms

Units can exhibit higher than normal parasitic drain on low voltage batteries if the telemetry module isn't commissioned in Valence to receive regular software updates.

Failure to correctly commission the telemetry module can also impede ability to receive diagnostic data on operation of units in the field.

Issue

Some unit have incorrect SIM number and module number on telemetry module recorded in the Valence system.

Solution

Remove the two 5 amp fuses for the telemetry module.

Labels :

Busses

Step Vans

Add tags



0 Kudos

Comment

