

**Problem Details:**

- M2 Plus with Cummins engines
- Virtual Regen Request switch is not enabled in ICUC
- Driver cannot manually request a regeneration

**FSPRs, FRACAS, DPR, Zeus:**

- FSPR 38919

**Affected Models / Truck options:**

- M2 Plus with Cummins engines built 5/9/23 through 3/28/24
- 19647 Units

**Responsible Supplier:**

- N/A

**Production Containment:**

- Inner bill change on module 28F BOMs to add parameter
- Effective date: 3/28/2024

No  Yes

**Field Containment (short term):**

- Fix as fail

No  Yes

**Root Cause:**

- Root cause complete
- Parameters were forgotten in redocumentation efforts

No  Yes

**Long Term Corrective Action Plan:**

- Inner bill change implemented long-term corrective action for programming
- Team responsible for programming has added this to their “lessons learned”

No  Yes

**Long Term Field Plan:**

- If different from Field Containment

No  Yes



Incorrect Vehicle



Operator's Manual