

Problem Details:

- Trucks were built with plain elbows. Should have chrome.
- Missed deviation chart resulted in wrong elbows being used
- Very easy to see discrepancy.

FSPRs, FRACAS, DPR, Zeus:

- Shopcall 554507

Affected Models / Truck options:

- WST 47X, 47X RHD, 48X RHD, 49X, 49X RHD
- 334 trucks total, 8 RHD

Responsible Supplier:

- N/A

Image/ Picture

Image / Picture

**Production Containment:**☒ No ☒ Yes

- Charts updated so correct elbow is called out.

Field Containment (short term):☒ No ☐ Yes

- Fix as Fail when customer complains.

Root Cause:☐ No ☒ Yes

- A missed deviation chart update resulted in specs being build post 1/8 changeover with standard vertical exhaust elbows when they called for chrome elbows.

☐ No ☒ Yes**Long Term Corrective Action Plan:**

- Ensure proper charts are loaded.

Long Term Field Plan:☐ No ☒ Yes

- Campaign to replace elbows with correct chrome plated elbows.