



SERVICE ACTION

Global Service Action
Number: N924

Subject: Air Conditioning Refrigerant Underfilled	Publication No.: N924
	Model: Range Rover (LK)
	Model Year: 2025
	Model: Range Rover Sport (L1)
	Model Year: 2025
	Date of Issue: 03 October 2024
Expiry Date: 31 October 2026	

To:	All National Sales Companies (NSCs), importers, retailers and authorized repairers.
For the Attention of:	The approved JLR retailer/authorized repairer.
Important:	<p>NOTE: The information in this campaign is intended for use by professional technicians. If you are not a JLR retailer/authorized repairer, do not assume that a condition described affects a specific vehicle. Contact an authorized JLR retailer/authorized repairer to determine if this campaign applies to a specific vehicle.</p> <p>This campaign has been issued to provide the relevant repair instructions, parts and warranty information. This campaign is valid for two years only. Repairs must be completed prior to the expiry date at the top of this campaign.</p> <p>This bulletin supersedes Update Prior to Sale (UPS) notice UPS3724-1 with immediate effect. The blue highlighted text relates only to the date information. All text in this bulletin should be read and understood in full.</p>

FOR THE ATTENTION OF ALL:

DESCRIPTION OF ISSUE

A potential concern has been identified on certain 2025 model year Range Rover and Range Rover Sport vehicles, where the Air Conditioning (A/C) system has been charged with the incorrect amount of A/C refrigerant.

ACTION TO BE TAKEN

At the next opportunity, you are requested to repair the vehicle.

Check the JLR Warranty Portal to make sure affected vehicles are correctly identified prior to starting this campaign. The Warranty Portal will be updated to reflect only those vehicles affected.

An owner may indicate that a repair has already been completed for this concern, in which case the full cost of the repair should be reimbursed. Refer to the warranty section of this campaign for details of the Customer Reimbursement and Related Damage Process. At the time of confirming a booking for a vehicle repair, make sure you check the Warranty Portal to confirm if there are any other outstanding campaigns, to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed in one visit.

	The following applies to: [NORTH AMERICA]
--	---

FOR THE ATTENTION OF NORTH AMERICAN TERRITORIES ONLY:

	The following applies to: [NORTH AMERICA]
--	---

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your JLR retailer/authorized repairer. Unsold vehicles must be repaired prior to handover of the vehicle for retail sale.

Yours faithfully

Steve Oldham

Global Customer Care Quality Director

SERVICE INSTRUCTION - N924

SROs

Description	SRO	Time
Air Conditioning (A/C) - Depressurize - Evacuate - Sweep and Recharge	82.30.02	0.4
Drive in/drive out	02.02.02	0.2

NOTE:

Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

Warranty Information

Warranty claims should be submitted quoting program code N924 with the relevant option code from the table below. As option codes are used there is no requirement for you to enter SROs or parts, these are included for information only.



The following applies to:
[ASIA PACIFIC, EUROPE, JAPAN, KOREA, MENA, NORTH AMERICA, OVERSEAS, Hong Kong, Taiwan]

NOTE:

* - An allowance equivalent to £80 Sterling, has been allocated to locally source SP-A2 refrigerant oil and [A/C](#) refrigerant.



The following applies to:
[ASIA PACIFIC, EUROPE, JAPAN, KOREA, MENA, NORTH AMERICA, OVERSEAS, Hong Kong, Taiwan]

Program Code	Option	Description	SRO	Time	Sundry Code	Qty/Value
N924	A	A/C - Depressurize - Evacuate - Sweep and Recharge	82.30.02	0.4	ZZZ999	£80.00
N924	B	A/C - Depressurize - Evacuate - Sweep and Recharge Drive in/drive out	82.30.02 02.02.02	0.4 0.2	ZZZ999	£80.00

NOTE:

The option that contains the drive in/drive out allowance may only be claimed when the vehicle has been brought back into the workshop for this action alone to be undertaken.

Warranty claims should be submitted in accordance with the current JLR Global Warranty Manual, and its amendments, unless stated otherwise in this campaign.

Customer Reimbursement and Related Damage Process

NOTE:

If there is a requirement to claim for related/consequential damage or customer reimbursement, refer to the related instruction that can be found in TOPIx (in the Search box, search for 'Related Damage Claim' and open the related bulletin link).

SERVICE INSTRUCTION

Total A/C System Capacity	HFO-1234yf	R134a
Vehicles With Auxiliary Climate Control	1000g	1150g
Vehicles Without Auxiliary Climate Control	800g	890g

1. Recharge the [A/C](#) system with the correct amount of refrigerant (see TOPIx Workshop Manual section 412-00: Climate Control System - General Information, Air Conditioning System Recovery, Evacuation and Charging).