

**SERVICE ACTION N928 – POWERTRAIN CONTROL MODULE SOFTWARE UPDATE**

SERVICE ACTION N928 – POWERTRAIN CONTROL MODULE SOFTWARE UPDATE	
AFFECTED MODELS	22-23MY Range Rover 23MY Range Rover Sport
VOLUME AFFECTED	US 114 CA 6
REPAIR	A concern has been identified on certain vehicles where the Software Over the Air (SOTA) updates are failing to be completed. This is due to the Powertrain Control Module (PCM) rejecting the update. A wired TOPIx software update to the PCM is required.
REPAIR TIME	0.2 hrs + DIDO
CAMPAIGN LAUNCH	September 26th , 2024
NOTES	Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory which cannot be delivered until the vehicle can be repaired. All other vehicles must have the repair completed at the next earliest opportunity