

UPDATE PRIOR TO SALE N924 – AIR CONDITIONING REFRIDGERANT UNDERFILLED

UPDATE PRIOR TO SALE N924 – AIR CONDITIONING REFRIDGERANT UNDERFILLED	
AFFECTED MODELS	25MY Range Rover and Range Rover Sport – P6 MHEV
VOLUME AFFECTED	US 679 CAN 239
REPAIR	A potential concern has been identified on certain vehicles, where the Air-conditioning (A/C) system has been charged with the incorrect amount A/C refrigerant. Retailers are requested to review the bulletin and evacuate then recharge the AC system with the correct amount of refrigerant.
REPAIR TIME	0.4 hrs. + DIDO
CAMPAIGN LAUNCH	August 30th, 2024
NOTES	Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory. All affected vehicles are being release from ports and will begin to arrive at your stores, please ensure to complete this repair prior to vehicle handover.