

## UPDATE PRIOR TO SALE N924 – AIR CONDITIONING REFRIDGERANT UNDERFILLED

UPDATE PRIOR TO SALE N924 – AIR CONDITIONING REFRIDGERANT UNDERFILLED	
AFFECTED MODELS	25MY Range Rover and Range Rover Sport – P6 MHEV
VOLUME AFFECTED	US 679 CAN 239
REPAIR	A potential concern has been identified on certain vehicles, where the Air-conditioning (A/C) system has been charged with the incorrect amount A/C refrigerant. Retailers are requested to review the bulletin and evacuate then recharge the AC system with the correct amount of refrigerant.
REPAIR TIME	0.4 hrs. + DIDO
CAMPAIGN LAUNCH	August 30th, 2024
NOTES	Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory. <b>All affected vehicles are being release from ports and will begin to arrive at your stores, please ensure to complete this repair prior to vehicle handover.</b>