

## ACCESSORY RUBBER FLOOR MATS INCORRECT

### Customer Voice:

- The second-row accessory floor mat does not fit properly.

### Technical Description:

- The accessory rubber floor mats provided with the Defender 130 model variants with the Captain's chair option have the incorrect second-row mat for the option.

### Status:

- **Retailer Bulletin 242509.025** was published to announce the error.
- The cost of the mats (\$300 MSRP) will be credited on the invoice.

### Defender

- 25MY Defender (130 with Captain's chair option only)

