

	Authored:	Aug 2024	Reference:	SOTA S024
	SOTA Campaign Release Summaries			
	Models:	All SOTA-capable vehicles (EVA2)		

Software-Over-The-Air (SOTA) Campaign Release Summaries

Please see below details of upcoming SOTA campaigns:

SOTA release N912 & H511

Vehicle scope (Model Line & MY)	<p>24MY Land Rover Defender, Discovery, Discovery Sport, Range Rover Evoque, Range Rover Velar, Range Rover Sport, Range Rover Jaguar E-PACE, F-PACE, XE, XF</p> <p>25MY Land Rover Range Rover Velar, Range Rover Sport Jaguar F-PACE, XE, XF</p>
Module(s) affected	ABS
Improvements overview	ABS diagnostic updates
Release type	Customer notified in-vehicle Single bank experience (vehicle shutdown required)
Customer impact	Vehicle required to be shut down and locked for approximately 30 minutes
'What's new?' customer release summary	<p>This release contains updates and improvements to vehicle on board diagnostics, fault detection, and resolves an issue where the park brake does not release when vehicle is stationary that may result in the display of an ABS warning.</p> <p>PHEV only: Please note that for a short period of time, you may experience some disruption in the EV capabilities after the update has completed. Please disconnect the vehicle charger and ensure the battery has a minimum charge level of 25% before starting the update.</p>