Bulletin No.: 24-NA-159

Date: October, 2024

## **TECHNICAL**

Subject: Water Leaks from Overhead Console or A-Pillars

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox EV	2024	2025	-	-	All	All

Involved Region or Country	North America, Brazil (Mercosur), Chile (West), Colombia (West), Ecuador (West), Uruguay (West), Japan
Additional Options (RPOs)	Equipped with ROOF - SUN, DUAL GLASS, OTR SLIDING, ELEC SUNSHADE (RPO CAJ)
Condition	Some customers may notice water present in cup holder or actively dripping from headliner.  Upon inspection, water may be dripping from the overhead console, the A-pillar on either driver or passenger side.
Cause	The cause of the condition may be the housing assembly may be leaking water and pooling up in the headliner.
Correction	Replace the sunroof housing assembly.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

**Important:** This technical service bulletin (TSB) can only be completed by certified repair facilities who have met all specific training, tool and equipment requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.

## **Service Procedure**

If you encounter a vehicle with the above concern, replace the sunroof housing assembly. Refer to *Sunroof Housing Replacement* in SI.

## **Parts Information**

Causal Part	Description	Part Number	Qty
Х	HOUSING ASM- SUN RF	85707522	1

Page 2 October, 2024 Bulletin No.: 24-NA-159

## **Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
6040290	Sunroof Housing Replacement	Use Published Labor Operation Time

Version	1
Modified	Released October 03, 2024