

REFERENCE:	TSB: 23-055-24 GROUP: 23 - Body	Date:	November 5, 2024	REVISION:	—
VEHICLES AFFECTED:	2024 - 2025 (B1) Jeep Renegade This bulletin applies to vehicles built on or after July 03, 2024 (MDH 0703XX) and on or before August 18, 2024 (MDH 0818XX).	MARKET APPLICABILITY:			
		<input type="checkbox"/> NA <input type="checkbox"/> CH <input type="checkbox"/> EE <input type="checkbox"/> IAP <input checked="" type="checkbox"/> SA <input type="checkbox"/> MEA			
CUSTOMER SYMPTOM:	Customers may comment on the following: <ul style="list-style-type: none"> Liftgate Sahara badge Fig. 1 is loose, detaching or deforming. 				
CAUSE:	Manufacturing issue				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 24-151 date of issue November 05, 2024. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.



Fig. 1
Sahara Badge

REPAIR SUMMARY:

This bulletin involves replacing the liftgate Sahara Badge.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-03-08-93	Badge, Replace (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.3 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1	7097396 - SA	Badge	Sahara

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the Repair Procedure. If any vehicle not on the VIN list exhibits the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Replace the Sahara badge [Fig. 2](#). Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 7055A83 - Emblema/Sigla/Moldura Porta Bagageiro ou Tampa Traseira - Remoção/Recolocação.



Fig. 2
Sahara Badge Location

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.