

Technical Service Bulletin (TSB)
Air Trapped in Steering Damper Warranty Extension XF1

REFERENCE:	TSB: 19-002-24 GROUP: 19 - Steering	Date:	November 7, 2024	REVISION:	23-041-24
VEHICLES AFFECTED:	**2018 (JK) Jeep Wrangler** 2018 - 2020 (JL) Jeep Wrangler **2018** - 2020 (JT) Jeep Gladiator This bulletin applies to **JL and JT** vehicles built on or before August 11, 2020 (MDH 0811XX).			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH	
CUSTOMER SYMPTOM:	A shimmy in the steering wheel after hitting an irregularity on the road surface (symptom is more prevalent in cold temperatures).				
CAUSE:	Air trapped in the steering damper				

This bulletin supersedes Technical Service Bulletin (TSB) 23-041-24, date of issue May 30, 2024, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include a new TSB number not highlighted with asterisks, an additional vehicle, model years, vehicles added to the build date, updated LOP and Spare Parts Table.

REPAIR SUMMARY:

This bulletin involves replacing the steering damper.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
**02-15-20-96	Damper, Steering – Replace (1 - Semi-Skilled)	19 - Steering	0.3 Hrs. **
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	52060058AH	Damper, Steering	JK Vehicles
1 (AR)	**68624107AA**	Damper, Steering	JT Vehicles
1 (AR)	CCUKV411AD	Damper, Steering	JL Vehicles

DIAGNOSIS:

If the customer describes any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Replace the steering damper. Refer to the detailed service procedures listed in DealerConnect>Service Library under: 19 - Steering / Linkage / Damper, Steering / Removal and Installation.

POLICY:

Vehicles included in this Technical Service Bulletin have a Warranty Extension to an 8 Year warranty extension or 144,840 km (90,000 mi) from in service date warranty period for this repair. See Warranty Bulletins: U.S. D-23-09 and Puerto Rico ID-23-10, for details associated with the Warranty Extension.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.