



# Service Bulletin

Bulletin No.: 22-NA-198

Date: October, 2024

## INFORMATION

**Subject: Information on Dimpling of Front Fascia Due to Incorrect Front Splitter Fasteners Installed at Pre-Delivery Inspection (PDI)**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette Z06, ZR1	2023	2025	—	—	—	—
	Corvette E-Ray	2024	2025	—	—	—	—


<b>Involved Region or Country</b>	North America, Europe, Middle East, Japan, Australia/New Zealand
-----------------------------------	--

**Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.**

### Service Procedure




6163496



6163499

During the installation of the front splitter kit, it is important to install using the correct fasteners.

There are four long fasteners included in the front splitter kit. They should **NOT** be used due to the longer fasteners possibly creating a dimple on the front fascia.



6163500

Fasteners A and B — Should use part number 11547755

**Important:** There will be 4 extra bolts of Part Number 11589012 in the original hardware kit after performing installation. These bolts can be discarded.

<b>Version</b>	3
<b>Modified</b>	Released October 06, 2022 Revised October 05, 2023 – Added the 2024 Model Year and added Europe and Japan to the Involved Region or Country section. Revised October 10, 2024 – Added the 2025 Model Year and the ZR1, E-Ray models.

