Bulletin No.: 24-NA-219

Date: October, 2024

TECHNICAL

Subject: Striker to Liftglass Latch Creak Noise

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models	- 2021	2025	-	-	All	All
Chevrolet	Suburban						
Cheviolet	Tahoe						
GMC	Yukon Models						

Involved Region or Country	North America
Condition	Some customers may comment on a creak noise coming from the rear liftglass.
Cause	The cause of the condition may be the striker sliding up and down on liftglass latch causing a creak/squeak.
Correction	Apply GM Super Lube generously on the latch forkbolt area.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.


Page 2 October, 2024 Bulletin No.: 24-NA-219

Service Procedure

Apply the grease to the locations shown below:



6748200



6748202

Note: The above picture is a Top Down view for reference.

Parts Information

Causal Part	Description	Part Number
N/A	Super Lube	12371287

Bulletin No.: 24-NA-219 October, 2024 Page 3

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2086718*	Apply Super Lube on Latch Forkbolt Area	0.2 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified Released October 08, 2024	