



Service Bulletin

Bulletin No.: 24-NA-083

Date: October, 2024

INFORMATION

Subject: EV Charge Inlet Dust Cover Replacement Information

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
BrightDrop	Zevo 400	2024	2024	-	-	All	All
	Zevo 600	2023	2024				
Cadillac	LYRIQ	2023	2025				
Chevrolet	Silverado EV	2024	2025				
	Blazer EV	2024	2025				
	Equinox EV	2024	2025				
	BrightDrop 400	2025	2025				
	BrightDrop 600	2025	2025				
GMC	HUMMER EV SUV	2024	2025				
	HUMMER EV Pickup	2022	2025				
	Sierra EV	2024	2025				

Involved Region or Country	North America
Condition	Some customers may comment on a missing or damaged HV charger port dust cover and tether.
Cause	The dust cover and tether are now released separately for Service.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Important: This technical service bulletin (TSB) can only be completed by certified repair facilities who have met all specific training, tool and equipment requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.

Service Procedure

Dust cover Part Number 24059685 is for Type 1 charger inlets used in North America (and other regions) but not all regions GM sells in.

Please review the GM Electronic Parts Catalog for proper use and Part Numbers.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*5086058	Replace DCFC dust cover	0.3 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	2
Modified	Released September 05, 2024 Revised October 18, 2024 – Added multiple models and Warranty Information.

