



## STAR ONLINE PUBLICATION




**Case Number:** S2402000003

**Release Date:** November 2024

**Symptom/Vehicle Issue:** Front Control Arm Bushing Has Rubber Peeled Away From The Bushing.

**Discussion:**



The above image is an ok condition and not a bushing failure. This flashing is not a functional part of the control arm front dog bone bushing and will cause no issue for the customer. No parts should be replaced for this appearance condition.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**