

2024-11-15

MODEL

Model	Model Description	Model Code
KA1	R 1300 GS	0M23
KA2	R 1300 GS Adventure	0M33
KR1	R 12 NINET	0N03
KR3	R 12	0N53

The affected vehicles have been marked with campaign number **0061640000** in AIR.

In order to determine if a specific motorcycle is affected by this campaign, it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair or take no further action. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

SITUATION

After a quality inspection it has been determined moisture/water can enter the right multifunction switch and cause malfunctions.

This issue does not impact vehicles with production dates of 07/01/2024 or later.

PROCEDURE

For vehicles that have not yet been delivered, the service action must be completed before vehicle handover. If the service action cannot be completed due to a parts shortage, the service action then must be performed during the next possible workshop visit when parts become available. In such instances, it is essential to inform the customer of the situation.

In all instances in which the vehicles have already been handed over to customers, the customers must be made aware of the situation described above and asked to have the Technical Campaign carried out.

The right multifunction switch must be replaced using the following repair instruction "61 31 073 – Replacing the multifunction switch on the handlebars on the right".

PARTS INFORMATION

Obtain and confirm the part numbers for your specific vehicle by entering the chassis number in ETK which takes into account specific equipment and/or options.

Additional parts like gaskets, hardware and chemicals may be required for the complete repair.

Part Number

61 31 5 B68 112	Right multifunction switch (US model code only)	QTY 1
-----------------	---	-------

CLAIM INFORMATION

Please submit claims via the normal claim process using the information below:

Defect code

00 61 64 00 00	Replacing the right multifunction switch
----------------	--

Copyright ©2024 MOTORRAD USA, a division of BMW of North America, LLC. All Rights Reserved

Labor Operation

00 60 448	Replace the right multifunction switch	5 FRU
+00 60 948	Replace the right multifunction switch	4 FRU
+46 52 510	Mounting and dismounting the rear-wheel stand with special tools (for motorbikes without a center stand)	1 FRU

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

Labor operation code 00 60 448 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation instead.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture_as_pdf 61 10 24 Replace Right Combination Switch.pdf](#)

