



SSM 53118 2025 Explorer - Non-Police Interceptor® Utility - Powertrain Malfunction (Wrench) Indicator With DTC P0929:77 Stored In The GSM - Built On Or Before 04-Nov-2024

Some 2025 Explorer vehicles, excluding Police Interceptor® Utility, built on or before 04-Nov-2024 may exhibit a powertrain malfunction (wrench) indicator with diagnostic trouble code (DTC) P0929:77 stored in the gear shift module (GSM). This may be due to the software in the GSM. To correct this condition, reprogram the GSM module using the latest software level in the Ford Diagnosis And Repair System (FDRS). For claiming, use causal part 7P155 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.