



SSM 53168 2024 Transit - Windshield Washer Fluid Leak At Washer Pump - Built On Or Before 22-Jul-2024

Some 2024 Transit vehicles may exhibit a windshield washer fluid leak at the washer pump built on or before 22-Jul-2024. This may be due to a washer fluid hose that has become disconnected from the windshield washer pump. To correct this condition, reinstall the line to the pump and add a locally obtained tie strap around the hose aligned with the washer pump port to secure the hose. For claiming, use causal part 17A605 and applicable labor operations in Section 11 of the Service Labor Time Standards (SLTS) Manual.