



SSM 53174 2015-2024 Various Vehicles - 2.7/3.0L Gas Engines - Incorrect Crankshaft Bolt In Parts Catalog

Various vehicles equipped with a 2.7L or a 3.0L gas engine may require a crankshaft bolt replacement during repairs. The parts catalog is incorrect and shows two crankshaft bolts available. The correct service part crankshaft bolt that must be ordered for these engines is FT4Z-6A340-A (will have "KX1" stamped on the head of the bolt). The parts catalog is in the process of being updated.