

LEAKING COOLANT PUMPS – 2.0L/P4

Customer Voice:

- Low coolant light on or smell of coolant from engine area.

Technical Description:

- The engine cooling pump has a visible coolant leak.

Status:

- Follow **TOPIX workflow**. It will direct you to:
 - Please inspect and take a photo of outer casting showing the whole component, with leak.
- Please raise a **FRED** for the attention of Local Engineering who will dispatch sample bottle.
- USE SAMPLE BOTTLE ONLY to take 4 ounce Coolant sample before repair.
- Dispatch coolant sample using FEDEX label provided.
- Retain removed water pump for collection via PRR.
- **This item will now be on the FRED list November 18th.**

TOPIX: 303-03B: Engine Cooling - INGENIUM I4 2.0L Petrol

Range Rover

- 20-24MY RR Evoque
- 18-24MY RR Velar

Discovery

- 21-24MY Discovery Sport

Jaguar

- 19-24MY E-PACE
- 18-24MY F-PACE
- 20-24MY F-TYPE
- 19-24MY XF
- 19-21MY XE

