

## ROOF BLIND OPERATION

### Customer Voice:

- The roof blind does not open or close properly.

### Technical Description:

- The roof wiring harness may be misrouted and interfere with the roof blind run channel.

### Status:

- SSM76211 has been published to provide repair instructions to address this concern.

### Range Rover

- 22 - 25MY RR Sport (L461)

