

<b>Reference</b>	SSM76222
<b>Models</b>	Defender / L663
<b>Title</b>	Roof Opening Panel Not Operating as Expected
<b>Category</b>	Body
<b>Last modified</b>	21-Nov-2024 00:00:00
<b>Symptom</b>	105000 Roof Options

**Content**      **Model / Model Year / Derivative**

DEFENDER / 20MY onwards / Vehicles with Roof Opening Panel

**Situation:**

JLR Engineering investigations have found reports of the Roof Opening Panel not opening or closing as expected.

**Action:**

Refer to the Service Information below.

**Service Information:**

Before following the 'Service Request,' complete the following steps.

1. Confirm the customer symptom is present.
2. If you identify that either the 'Roof Opening Panel Motor' or 'Roof Opening Panel Blind Motor' require renewing, continue to the 'Service Request' below.

**Service Request:**

**Do not replace any components.**

1. Raise a Technical Assistance (TA).

The TA must include the following information:

- State which motor requires renewing.
- A video clip of the customer's symptom.
- Reference the following engineering department: 'BES\_305 Glazing and Roofs' and this SSM number (76222).

2. A JLR engineer will assess the TA and provide further guidance.

(Ref 000386388)