

SS 773-WST Optimized Idle icon missing on instrument cluster

Applicable Vehicles

Model Year 2024 Western Star vehicles equipped with Optimized Idle.

Symptoms

While Optimized Idle is running the icon or telltale does not illuminate. See figure 1. This icon does not prevent the Optimized Idle feature from functioning.

Issue

A bug with model year 2024 software in the instrument cluster can cause the Optimized Idle icon to not illuminate.

Solution

This will be fixed in the model year 2025 software package. Model year 2024 vehicles will **not** be compatible with model year 2025 software.

Figure 1

MY24

MY25



Labels :

- 47X
- 49X
- 57X

Add tags



0 Kudos

Comment