


SPEEDMASTER AND BOBBER ACCESSORY CLUTCH CABLES

TMA has been made aware that the clutch cable (T9630240) included in high bar cables accessory kits for the Bobber (A9630253) and the Speedmaster (A9630662) could be the incorrect length. The approximate correct cable length is 138mm long beginning at the exposed section of the cable, as opposed to the incorrect cables that are approximately 150-160mm long. We would ask that, using the image below as a reference, that you check any stock of this cable or the kits to determine if you have an affected unit. If so, please email TMA Aftersales to have a replacement cable sent at no cost.



If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.