

SCRAMBLER 400 X & SPEED 400 KEY PAIRING

Triumph is aware of a problem currently affecting the key pairing functionality of TDT on Speed 400 and Scrambler 400 X models. You will currently be unable to pair replacement keys to these models. A fix has been released as part of the next TDT update, which has been released as TOL #29131-SVC. Note that new immobilizer units are shipped with keys already paired and only require immobilizer/ECM pairing. This functionality is unaffected by this error.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.