



Bulletin No.: PIC6564A
Published date: 11/4/2024

Preliminary Information

PIC6564A Diagnostic Tip: For Adding Trailer Lighting Or Trailer Lights Inoperative For Vehicles Built Without RPO: V92

Models

Brand: Cadillac XT4 **Model:** XT4 **Model Years:** 2024 - 2025 **VIN:** All **Engine:** All All **Transmissions:** All

Involved Region or Country	North America
Addition options (RPO)	Without V92 (TRAILER PROVISIONS) V08 (HEAVY DUTY COOLING SYSTEM)
Condition	Customers may inquire about adding a trailer hitch and/or trailer lighting or a technician may find that the trailer lighting is inoperative.
Cause	Calibrations for trailer lighting are not available for vehicles built without RPO option V92.

Correction:

No repairs or attempts to install a trailer hitch or trailer lighting should be performed.

Engineering is aware of this condition and is working on an updated software to remedy this concern.

This PI will be updated or a TSB will be released when the fix is available.

Version History

Version	2
Modified	07/30/2024 - Created on. 11/04/2024 - Updated Correction.