



**Bulletin No.:** PIT6280

**Published date:** 11/8/2024

## Preliminary Information

### PIT6280 Illuminated Perimeter Rocker Lighting Inoperative

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Chevrolet Blazer EV		2025	All All	All	All
Chevrolet Silverado EV		2025	All All	All	All
GMC Sierra Denali EV		2025	All All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Additional Options (RPO)</b>	<b>S3I</b>
<b>Condition</b>	<b>Dealer installed accessory perimeter rocker panel lighting kit is inoperative.</b>
<b>Cause</b>	<b>Software Anomaly</b>

#### Correction:

**Do not attempt any repairs at this time.**

**Advise the customer that engineering is working on updated software for this concern.**

**A bulletin will be released when updated software is available.**

#### Additional SI Keywords

accessory, dealer, ground, lamp, inop, inoperative, installed, light, lighting, lights, panel, puddle, rocker, SPO

#### Version History

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>11/08/2024 - Created on.</b>

 GM Global Brands

© 2024 General Motors. All Rights Reserved.