



Technical Service Bulletin

91 PSS MIB3: radio plays when vehicle is parked

91 24 83 2074400/2 November 22, 2024. Supersedes Technical Service Bulletin Group 91 number 24-26 dated July 1, 2024 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q4 e-tron, and Q4 Sportback e-tron	2022 – 2024	All	MIB3

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Service</i> (updated expected software release date)
1	07/01/2024	Initial publication

This bulletin applies to MY 2022 – 2024 Q4 e-tron, and Q4 Sportback e-tron.

Customer states:

- The radio plays when the vehicle is parked.
- Sometimes, when this happens, the MMI screen is black.
- When the driver door is opened, the radio usually stops.

Workshop findings:

- The complaint occurs only sporadically and can be difficult to reproduce.

Technical Background 1

Software issue

Production Solution

Week 45/2023

Service

1. Explain to the customer that a solution is expected to be available by the end of the 3rd quarter of 2025 (subject to change) and that no repairs are necessary at this point.



Technical Service Bulletin

2. Do not replace any components for this condition since this will not resolve the customer's concern.
 3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).
- This behavior can occur intermittently when leaving the vehicle.
 - The radio starts playing after about one minute.
 - If the radio plays while the doors are closed (with the vehicle already locked), opening the driver door can deactivate the audio output.

NOTICE

Only opening the driver door can deactivate the audio output.

- **If other doors or the trunk is opened, the audio output will not be deactivated.**
- **After a few minutes (< 5 minutes), the system will automatically turn off.**
- **This cannot damage or drain the battery completely.**

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Do not replace parts or attempt repairs. Unjustified labor / replacement parts will be debited. **Invoicing under warranty is not permitted.**

Additional Information

All part and service references provided in this TSB (**2074400**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.