



Technical Service Bulletin

93 Audi e-tron GT: vibrations at high speeds

93 24 33 2075983/1 November 15, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2022 - 2025	All	Not Applicable

Condition

Customer states:

Vibrations above 75Mph (120 km/h).

Workshop findings:

The complaint can be reproduced.

Technical Background 1

There are multiple possible causes of the complaint. To find out the cause of the complaint, please use the attached measuring and analysis instructions.

If the complaint can be traced to the wheels (first, second, and third wheel order), please use TSB: 2074846 for the further procedure.

If the complaint can be traced to the front axle powertrain order (third wheel order only), the characteristics are as expected. There is no reason to repair the drive system in this case.

Production Solution

Not applicable.

Service

Try to reproduce the customer complaint (based on the description/cause of the issue), so that it can be clearly assigned to this TSB.

When performing the analysis, you should ideally use the VAS tool 611015 (PICO NVH tool) to identify the noise with the measuring set-up described below. When performing analysis and billing with VAS 611015, please also observe TSB: 2063427.

Details about the configuration and positions of the measurement are provided in the document for the e-tron GT which is attached to TSB: 2063427.



Technical Service Bulletin

Details about evaluating the measurement are provided in the attached document.

Warranty

When performing analysis and billing with VAS 611015, please also observe TSB: 2063427.

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9340		
Damage Code:	0020		
Labor Operations:	Set-up time for PICO noise analysis tool	0161 0000	See SRT with associated operations
	Road test prior to the service procedure	0121 0002	10 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB 2075983/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2075983**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.