



**Bulletin No.:** PIT6282A  
**Published date:** 11/18/2024

## Preliminary Information

**PIT6282A Possible Stall Or No-Start . Starter Clicks. DTCs U0140 U0401 U0402 U1611 U1627 U1643 U1818 U1962 U197A U3003 B1A7A Possible**

### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Chevrolet	Equinox	2025	All All	All	All
GMC	Terrain	2025	All All	All	All

<b>Involved Region or Country:</b>	<b>North America</b>
<b>Condition:</b>	<b>Customer may experience a stall or no-start with a clicking starter when the Start button is pressed. Any of the following DTCs may be present. U0140 U0401 U0402 U1611 U1627 U1643 U1818 U1962 U197A U3003 B1A7A</b>
<b>Cause:</b>	<b>G111 and/or G112 may not be properly torqued.</b>

### **Correction:**

Inspect G111 and G112 to confirm they are torqued to specifications. Refer to eSI for specifications. If clean and tight, continue with diagnosis.

### Version History

<b>Version</b>	<b>2</b>
<b>Modified</b>	<b>11/12/2024 - Created on. 11/18/2024 - Updated Models</b>

 GM Global Brands

© 2024 General Motors. All Rights Reserved.