



Preliminary Information

PIT6289 Collision / Detection Systems Alert Type Keeps Changing

Models

Brand:	Model:	Model Years:	VIN: from	to	Engine:	Transmissions:
Cadillac	Escalade	2022 - 2024	All	All	All	All
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)	2022	All	All	All	All
Chevrolet	Silverado 1500	2023 - 2024	All	All	All	All
Chevrolet	Suburban	2022 - 2024	All	All	All	All
Chevrolet	Tahoe	2022 - 2024	All	All	All	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)	2022	All	All	All	All
GMC	Sierra 1500	2023 - 2024	All	All	All	All
GMC	Yukon	2022 - 2024	All	All	All	All

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Involved Region or Country	North America, Mexico, Europe, Uzbekistan, Russia, Middle East, Iraq, Israel, Palestine, Argentina, Brazil, Bolivia, Chile, Colombia, Ecuador, Paraguay, Peru, Uruguay, Venezuela, Japan, Cadillac Korea (South Korea), GM Korea Company, China - SGM, Taiwan , Thailand, Singapore, Philippines, Australia/New Zealand, Egypt, South Africa
Condition	<p>A customer may have a concern that after setting Collision / Detection Systems Alert Type warning to audible beep, it will change to Safety Alert Seat (haptic) on its own.</p> <p>This typically occurs after several days of driving.</p>
Cause	Unknown at this time

Correction:

Engineering is aware of this issue and are working on a repair.

No parts should be replaced at this time.

The PI will be updated with repair information when it becomes available.

Version History

Version	1
Modified	Created on 11/20/24